

Geometric Symbols

Symbol	Description	Geometry
	ANGULARITY	ORIENTATION
	CONCENTRICITY	LOCATION
	CYLINDRICITY	FORM
	FLATNESS	FORM
	PARALLELISM	ORIENTATION
	PERPENDICULARITY	ORIENTATION
	POSITION	LOCATION
	PROFILE	PROFILE
	PROFILE OF A LINE	PROFILE
	CIRCULARITY	FORM
	RUNOUT	RUNOUT
	STRAIGHTNESS	FORM
	SYMMETRY	LOCATION
	TOTAL RUNOUT	RUNOUT

Symbol	Modifier
	FREE STATE
	LEAST MATERIAL CONDITION
	MAXIMUM MATERIAL CONDITION
	PROJECTED TOLERANCE ZONE
	REGARDLESS OF FEATURE SIZE
	TANGENT PLANE
	UNILATERAL